



Structure Inventory and Appraisal

Bridge ID: 129561 FHWA No.: 129561	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>Official</td> <td>SR:</td> <td>SD/FO:</td> </tr> <tr> <td>Unofficial</td> <td>SR: 89.8</td> <td>SD/FO: Not Deficient or Obsolete</td> </tr> </table>	Official	SR:	SD/FO:	Unofficial	SR: 89.8	SD/FO: Not Deficient or Obsolete
Official	SR:	SD/FO:					
Unofficial	SR: 89.8	SD/FO: Not Deficient or Obsolete					
IDENTIFICATION 7 Facility Carried: L AVE 5B Rte. Signing Prefix: 4 5C Level of Service: 1 - MAINLINE 5D Inventory Route: 00000 City: RURAL 3 County: 024 - Crawford 9 Location: 084403503 5E Directional Suffix: 0 - NOT APPLICABLE 6 Feature Intersected: MINOR DRAINAGE 2 District: 0 Garage: 000 98 Border Bridge Code: % Responsibility: 99 Border Bridge No.:	INSPECTION 90 Inspection Date: 05/08/2014 Next Routine Insp Date: 05/08/2016 Inspection Agency: 93A FC Inspection Date: 92A FC Frequency: 93B UW Inspection Date: 92B UW Frequency: 93C SI Date: 92C SI Frequency: Other Non-NBI Date: Other Non-NBI Freq.:						
STRUCTURE TYPE AND MATERIALS 43A Main Span: 3 - Steel 43B Main Span Design: 02 - Stringer/Multi-beam or Girder 45 No. Spans Main Unit: 1 44A Appr. Span: 000 - NA 44B Appr. Span Design: 000 - NA 46 No. of Appr. Spans: Near 0 Far 0 107 Deck Type: 8 - Wood or Timber 108A Wearing Surface: 8 - Gravel 108B Membrane: 0 - None 108C Deck Protection: 0 - None	CONDITION 58 Deck: 9 - Excellent Condition 59 Super: 9 - Excellent Condition 60 Sub: 9 - Excellent Condition 61 Channel/Channel Prot.: 8 - Banks are protected 62 Culvert: N - Not Applicable						
GEOMETRIC DATA 48 Length Max Span: 38.0 ft. 49 Structure Length: 39.7 ft. 34 Skew: 0° Deck Area: 956.77 sq. ft. 50B Curb/Sdwk Width R: 0.0 ft. 50A Curb/Sdwk Width L: 0.0 ft. 51 Width Curb to Curb: 24.1 ft. 52 Width Out to Out: 24.1 ft. 32 Appr. Roadway width: 22 ft. (w/ Shoulders) 33 Median: 0 - No median 35 Structure Flared: 00 - No flare 10 Vertical Clearance: 99'99" 47 Horiz. Clearance: 16'10" 53 Min. Vert. Clearance Over: 99'99" 54B Min. Vert. Underclearance: 00'00" 55 Min. Lat. Underclearance R: 00'00" 56 Min. Lat. Underclearance L: 00'00"	APPRAISAL 67 Str. Evaluation: 6 - Equal to present minimum criteria 68 Deck Geometry: 6 - Equal to present minimum criteria 69 Underclear Vert & Horiz: N - Not applicable 71 Waterway Adequacy: 8 - Bridge Above Approaches 72 Approach Alignment: 6 - Equal to present minimum criteria 36A Bridge Rail: 0 - DOES NOT MEET CURRENT SAFETY STANDARDS, OR IS NOT THERE AND IS NEEDED. 36B Transition: 0 - DOES NOT MEET CURRENT SAFETY STANDARDS, OR IS NOT THERE AND IS NEEDED 36C Approach Rail: 0 - DOES NOT MEET CURRENT SAFETY STANDARDS, OR IS NOT THERE AND IS NEEDED 36D Approach Rail Ends: 0 - DOES NOT MEET CURRENT SAFETY STANDARDS, OR IS NOT THERE AND IS NEEDED 113 Scour Critical: 8 - Stable - Excellent Condition						
NAVIGATION DATA 38 Navigation Control: 0 - No navigation control on waterway (bridge permit not required) 111 Pier Protection: 39 Vertical Clearance: 0'00" 40 Horiz. Clearance: 0'00"	LOAD RATING AND POSTING 31 Design Load: 0 - Unknown 63 Rating Method: 2 - Allowable Stress (AS) reported in english tons using HS-20 loading. 64 Operating Rating: 32.4 Tons 65 Rating Method: 2 - Allowable Stress (AS) reported in english tons using HS-20 loading. 66 Inventory Rating: 27.0 Tons 70 Posting: 5 - Equal to or above legal loads 41 Posting Status: A - Open						
16 Latitude: 42.05172909 17 Longitude: -95.46650216	AGE AND SERVICE 27 Year Built: 2013 Design No.: 0 106 Year Reconstructed: 42A Type of Service on: 1 - Highway 42B Type of Service Under: 5 - Waterway 28A Lanes on: 2 28B Lanes under: 0 29 ADT: 5 30 Year of ADT: 2012 109 Truck ADT: 0 % Speed Limit: 55 19 Detour Length: mi.						
FRA No. (if RR Bridge): Mile Post:	CLASSIFICATION 112 NBIS Length: Y 26 Functional Class: 09 - Rural - Local 100 STRAHNET: 0 - Not a defense highway 101 Parallel Structure: N - No parallel structure 102 Direction of Traffic: 2 - 2-way traffic 22 Owner: 02 - County Highway Agency 21 Custodian: 02 - County Highway Agency 37 Historical Significance: 5 - Not eligible 75A Type of Work Proposed: 76B Work Done by:						