

2827 9-19-39 - Dug - 12x14x14 hole
 3334 in cen. of infans. No of rods

Farmers says cen. was 5' below
 out when dam was built at
 foot of hill

- Ties from X nails
- 66.6 S.E. from large Power Pole
- 44.3 S.W. from Corner Post
- 56.1 N.W. from Brass Post
- 79.2 N.E. from Power Pole
- 75.5 N.E. from Gate Post

4/22/86 Set 1" iron rebar from
 split of power pole lines.
 fences, and other available
 information, as directed
 by Co. Engr. H. Dale Wight
 # 5798

Sec. Con. Established for
 Bridge work on Co. Rd North

