Crawford County Recorder Denise Meeves Fee Book 2008-2425

08/25/2008 @09:32AM PLC PLAT CORNER CER Book: Page: \$7.00 # Pages: 1

Lee O. Gallentine LS, Ryken Engineering, 511 Bank St., Webster City, IA 50595 - Ph 515-832-1876 Fax 516-832-1932

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF

Land Survey Monuments situated in Section 18 , Township **83** North, Range 37 West, of the Fifth Principal Meridian, Crowford County, Iowa, Previously recorded in Inst. #2002-3978

in County Recorder's Office

This corner was used for a survey in this section for Ray P. and Carol A. Lenz and Larry W. and Jean A. Boeckman. Bosis of bearing for this corner cert, can be found on the associated plat of survey filed in the Co. Rec's Office for this section.

Legend

BC = Noil with Bottle Cop
BP = Brace Post
CP = Corner Post
CMP = Cornugated Netol Pipe
CM = 4* Sq Concrete Monument with
1/2** iron rerod in center (tie to rerod)
CX = Cut 'X'
GP = Gate Post

ID = Inside Diarneter
OD = Outside Diarneter
PP = Power Pole
PW = Nail with Yellow Plastic Washer
RCP = Reinforced Concrete Pipe
RH = Red Head (Nail in wire)
ROW = Right of Way
RW = Nail with Reflective Round Washer

R/W = Iron ROW Roll
SFP = Steel 'T' Post
SW ≈ Noil with Square Metal Washer
TP ≈ Telephone Pedestal
TW = Noil with Round Metal Washer
WFP = Wood Fence Post
X ≈ X Nails



Center

Set IW In top of WFP -Q 1.30' 🛦 · O----- x --

Monument Description, Remarks, and Plan View:

Center - History of Comer =

1909, Sep. 7 - 'Lime Stone + Brick Bats' per Co. Engr's MC Field Bk 59 Pg 58.

2002, Dec. 2 - 'SET %' REBAR WITH RED PLASTIC CAP STAMPED."S. SHEVEL 118:0" ' by J Scott Shevel per Co. Rec's Inst.

#2002-3976 and Inst. #2002-3978.

Co Engr's previous and current ties do not indicate that corner is monumented.

Searched area with metal detector and found \(\) or red capped iron rerod (\(\) (11810) 0.3' exposed on southwest side of cut off power pole in—line with fencelines West and South, 0.5'\(\) West of fenceline North, and 0.5'\(\) South of fenceline East. Searched 1.0'\(\) x 4.0' deep area around rerod with tile probe and found nothing. Exacovated 1.5'\(\) x 2.0' deep hole around corner post and found nothing. Searched hole to 4.5'\(\) deep with tile probe and found nothing. Nonument found matches that of record and record ties are within reason. Therefore, used rerod as the correct corner. All ties are plumb distance unless indicated otherwise.

This certificate is being prepared because there are no longer three valid ties of record.



I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed land Surveyor under the laws of the State of lows.

LEE O. GALLENTINE, LS
Date: 7 25 7016 license number. 15745

My license renewal date is December 31, 2008

Pages or sheets covered by this seal: 1

List Corners to be Indexed Corners Section Twp Range

>, PL 5

P:\808\CRAWFORDCO\\$188337\PRESTACE4668\dwg\