WARDER C. HILLHOUSE, JR. MHF ENGINEERING P.C. 300 W. McKINLEY JEFFERSON, IA. (515)386-4101

UNITED STATES PUBLIC LAN Land Survey Monuments in Section 40, of the Fifth Principal Previously recorded in (book, page, docur (Show reason for preparing this certificate, the corner positions and monumentation foun Monument Description and Remarks:	10 Meridian, nent number, etc e evidence an	, Township CRAWFORD in Cour	82 Conty Recor	ounty, Io der's Of	ange wa. fice.
DI	AN – VII	r TA Z	· · · · · · · · · · · · · · · · · · ·		
(Show a minimum of three reference ties to			nt monum	onte and	physical
conditions that will enable recovery of the co		ai objects, releva	iic monum	ients and	physical
CENTER 10-82-40	C1	/4 COR, 10-82-40		/8"x30" /w/cap	
Q	<u>.</u> 1	"X" NA	LS #6806		Α
SURVEY MARKER IN TOP OF POST	· · · · · · · · · · · · · · · · · · ·	PWR. PC	LE CONTRACTOR		1 2
FND. I. PIN 587.90' BOX CULVER!	(FND. LEAD PLU	(i) = ⁸ ^y			
BLOCK 21 DOW CITY 27.10' CENTER	(1110) EEND 1 EO	55.00' 112.1	l	}	A - A
25.00'	2592.03	· - т — * ''	AVENUE (E59)		
SET 5/8 X30 REROD/W/CAP		52.38		. li.	
#6806 TO WITNESS	31.20	- S- (/ I	X" NAILS PWR. POLE		
33,1121		8 8			į.
USED PINS FOUND ON BLOCKS 21 AND 22 OF DOW CITY TO ESTABLISH CORNER LOCATION. SET 5/8"X30" REROD/W/CAP #6806 25.00 FEET EAST OF CORNER ON SOUTH LINE OF NORTHEAST QUARTER TO WITNESS CORNER LOCATION		4 4			
ST 000 40 80 40	*	NE COR. 10-82-40)		N
SE COR. 10-82-40	SOUTH MOST		•		1
	COR. WING WALL	BRIDGE	SOUTH MOST COR. WING WA	O.	
(9) Sel CENTER PHONEBOX	ļ		CON. MING WA	CL .	И
9 8 50.97'	}	468.14' 337.08' /			
78.00' GARAGE	305.6	_/ /- \$	TEEL POST		
ORACOR 177.76' NW COR.	L "X" NAILS	, 4	,		
77.76' NW COR.	COR. POST	1.60'			
PAVING		NE WHICH APPEARS TO BE			
SHOWN ON AERIAL FROM 1938 AND EXTENSION OF EAST LINE OF SOUTHEAST QUARTER TO ESTABLISH CORNER LOCATION. NO RECORD OF CORNER SINCE ORIGINAL SURVEY OF TOWNSHIP. SET 5/8"X30"				RECORD	
7,0010 7, 117,12, 325	OF CORNER SIN	REROD/W/CAP #68		/6 /50	
I hereby certify that land surveying document	and the	List Cor	ners to b	e Indeve	1
related survey work was performed by me or	under my		Section		
direct personal supervision and that I am a duly licensed land surveyor under the laws of the state of Iowa.		Corners		Twp	Range
		NE COR. SE COR.	10 10	82 82	40 40
Signature: Marke C. Hillhouse, Jr.		E1/4 COR.	10	82	40
Date: 10/10/01 Lic. No.	6806	CENTER	10	82	40
, , , , , , , , , , , , , , , , , , ,		NW COR.	11	82	40
License Renewal Dec. 31, 2001	SW COR. W1/4 COR.	11 11	82 82	40 40	
Date Surveyed: 10/01	** * * * * * * * * * 	1 17 7 COIN.	•	02	70

WARDER C. HILLHOUSE JR. 6806

CENTER	10	82	40		
NW COR.	11	82	40		
SW COR.	11	82	40		
W1/4 COR.	11	82	40		
SE COR.	3	82	40		
SW COR.	2	82	40		
	File No. 01177-2				



M.H.F. ENGINEERING, P.C. ENGINEERS – LAND SURVEYORS Jefferson, Iowa 50129 Ph. (515)386–4101

Seal