

PREPARED BY: MICKAEL BERNDT CRAWFORD COUNTY ENGINEERS OFFICE - COURTHOUSE - DENISON, IA. - 712-263-2449

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF

LAND SURVEY MONUMENT SITUATED IN SECTION $\,28\,$, $\,T\,$ 83 N, $\,R\,$ 38 W $\,$ OF THE 5TH P.M. CRAWFORD COUNTY, IOWA.


PREVIOUSLY RECORDED IN BOOK N/A , PAGE , OTHER

MONUMENT DESCRIPTION AND REMARKS

EAST1\4 CORNER SEC.28-83-38


This corner was not set by the government surveyors during the original survey of East Boyer Township. The corner was established by the split of the NE Cor. Sec.28-83-38 and the SE Cor. Sec.28-83-38 and the split of the fences compared to the split of the road. The original road #84 was established in 1872. Crawford County was grading the road and needed the corner for alignment purposes.

EAST 1\4 CORNER SEC. 28-83-38 SET 5\8" X 18" REBAR RED CAP #11982 6" DEEP



CORNER E1\4
SECTION 28
TOWNSHIP 83N

RANGE 38W



I HEREBY CERTIFY THAT THIS LAND SURVEYING DOCUMENT WAS PREPARED AND THE RELATED SURVEY WORK WAS PERFORMED BY ME OR UNDER MY DIRECT PERSONAL SUPERVISION AND THAT I AM A DULY LICENSED LAND SURVEYOR UNDER THE LAWS OF THE STATE OF IOWA.

P ", J. ASSMAN

01/16/01 DATE

IA: LICENSE NO. 11982

EXP. DATE 12-31-02

PAUL J.
ASSMAN
11982