INDEXED FOLLOW UP PROOFFD SCANNED

Δ

◬

△

 $\triangle$ 

REC006217

Crawford Co FEE BOOK 2005-1039 4/ PLC PLAT CORNER CERBOOK:

Total Fees:

WARDER C. HILLHOUSE, JR. MHF ENGINEERING P.C. 300 W. McKINLEY JEFFERSON, IA. (515)386-4101


## UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF


., Range Land Survey Monuments in Section\_ 18 , Township 37 , of the Fifth Principal Meridian, \_\_\_\_\_ Previously recorded in \_\_\_\_\_\_\_(book, page, document number, etc.) \_County, Iowa. CRAWFORD <u>in County Recorder's Office.</u> (Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)

Monument Description and Remarks: CORNERS LOCATED FOR SURVEY WORK IN SECTION


## PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)





FOUND 1" IRON PIN IN CONCRETE CENTER SEC. 18-T84N-R37W



S1/4 COR. SEC. 18-T84N-R37W

FOUND PK NAIL IN CONCRETE

I hereby certify that this land surveying document and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed land surveyor under the laws of the state of lowaring and the state of lowaring the laws of lowaring the laws of the state of lowaring the laws of lo

FOUND PK NAIL IN CONCRETE

License Renewal Dec. 31, 2005

Date Surveyed: 3/23/05

WARDER C HILLHOUSE JR. AWOL

6806

| List    | Corners to | be Indexed |       |
|---------|------------|------------|-------|
| Corners | Section    | Twp        | Range |
| W 1/4   | 18         | 84         | 37    |
| N 1/4   | 18         | 84         | 37    |
| S 1/4   | 18         | 84         | 37    |
| CENTE   | R · 18     | 84         | 37    |

File No. 05041-1



M.H.F. ENGINEERING, P.C. ENGINEERS - LAND SURVEYORS ferson, lowa 50129 Ph. (515)386-4101

Seal

/19/2005