



Structure Inventory and Appraisal

Bridge ID: STOCKHOLM-130071
 FHWA No.: 130071

Official	SR:	SD/FO:
Unofficial	SR: 92.8	SD/FO: Not Deficient or Obsolete

IDENTIFICATION

7 Facility Carried: 290TH ST
 5B Rte. Signing Prefix: 4
 5C Level of Service: 1 - MAINLINE
 5D Inventory Route: 00000
 City: RURAL
 3 County: 024 - Crawford
 9 Location: .50 MI S NW Cor 5-85-38
 5E Directional Suffix: 0 - NOT APPLICABLE
 6 Feature Intersected: NORSKY CREEK
 2 District: 0
 Garage: 000
 98 Border Bridge Code:
 % Responsibility:
 99 Border Bridge No.:

INSPECTION

90 Inspection Date: 03/30/2016
 Next Routine Insp Date: 03/30/2018
 Inspection Agency: 2 - County
 93A FC Inspection Date:
 92A FC Frequency:
 93B UW Inspection Date:
 92B UW Frequency:
 93C SI Date:
 92C SI Frequency:
 Other Non-NBI Date:
 Other Non-NBI Freq:

Inspection Type: N/A
 91 Frequency: 24
 Next Insp Type: In-Depth
 Inspection Group: Crawford County
 Next FC Insp.: NA
 Next UW Insp.: NA
 Next Spec. Insp.: NA
 Next Other Insp.: NA

STRUCTURE TYPE AND MATERIALS

43A Main Span 3 - Steel
 43B Main Span Design: 02 - Stringer/Multi-beam or Girder
 45 No. Spans Main Unit: 001
 44A Appr. Span 000 - NA
 44B Appr. Span Design: 000 - NA
 46 No. of Appr. Spans: Near 0000 Far 0000
 107 Deck Type: 8 - Wood or Timber
 108A Wearing Surface: 7 - Wood or Timber
 108B Membrane: 0 - None
 108C Deck Protection: 0 - None

CONDITION

58 Deck: 8 - Very Good Condition (no problems noted)
 59 Super: 8 - Very Good Condition (no problems noted)
 60 Sub: 8 - Very Good Condition (no problems noted)
 61 Channel/Channel Prot.: 6 - Bank slump, widespread minor damage
 62 Culvert: N - Not Applicable

GEOMETRIC DATA

48 Length Max Span: 51.5 ft.
 49 Structure Length: 52.5 ft.
 34 Skew: 0°
 Deck Area: 1275.75 sq. ft.
 50B Curb/Sdwk Width R: ft.
 50A Curb/Sdwk Width L: ft.
 51 Width Curb to Curb: 24.3 ft.
 52 Width Out to Out: 24.3 ft.
 32 Appr. Roadway width: 26.0 ft.
 (w/ Shoulders)
 33 Median: 0 - No median
 35 Structure Flared: 00 - No flare
 10 Vertical Clearance: 99'09"
 47 Horiz. Clearance: 24'03"
 53 Min. Vert. Clearance Over: 99'09"
 54B Min. Vert. Underclearance: 00'00"
 55 Min. Lat. Underclearance R: 00'00"
 56 Min. Lat. Underclearance L: 00'00"

APPRAISAL

67 Str. Evaluation: 6 - Equal to present minimum criteria
 68 Deck Geometry: 6 - Equal to present minimum criteria
 69 Underclear Vert & Horiz: N - Not applicable
 71 Waterway Adequacy: 8 - Bridge Above Approaches
 72 Approach Alignment: 8 - Equal to present desirable criteria
 36A Bridge Rail: 0 - DOES NOT MEET CURRENT SAFETY STANDARDS, OR IS NOT THERE AND IS NEEDED.
 36B Transition: N - FEATURE NOT REQUIRED
 36C Approach Rail: N - FEATURE NOT REQUIRED
 36D Approach Rail Ends: N - FEATURE NOT REQUIRED
 113 Scour Critical: 8 - Stable - Excellent Condition

NAVIGATION DATA

38 Navigation Control:
 0 - No navigation control on waterway (bridge permit not required)
 111 Pier Protection: 2 - In place and functioning
 39 Vertical Clearance: "
 40 Horiz. Clearance: "

LOAD RATING AND POSTING

31 Design Load: 0 - Unknown
 63 Rating Method: 2 - Allowable Stress (AS) reported in english tons using HS-20 loading.
 64 Operating Rating: 32.5 Tons
 65 Rating Method: 2 - Allowable Stress (AS) reported in english tons using HS-20 loading.
 66 Inventory Rating: 27.0 Tons
 70 Posting: 5 - Equal to or above legal loads
 41 Posting Status: A - Open

16 Latitude: 42.2035223 17 Longitude: -95.30396239

AGE AND SERVICE

27 Year Built: 2015 Design No.: 0
 106 Year Reconstructed:
 42A Type of Service on: 1 - Highway
 42B Type of Service Under: 5 - Waterway
 28A Lanes on: 2 28B Lanes under: 0
 29 ADT: 30 30 Year of ADT: 2012
 109 Truck ADT: 30 % Speed Limit: 55
 19 Detour Length: 4 mi.

FRA No. (if RR Bridge):
 Mile Post:

CLASSIFICATION

112 NBIS Length: Y
 26 Functional Class: 09 - Rural - Local
 100 STRAHNET: 0 - Not a defense highway
 101 Parallel Structure: N - No parallel structure
 102 Direction of Traffic: 2 - 2-way traffic
 22 Owner: 02 - County Highway Agency
 21 Custodian: 02 - County Highway Agency
 57 Historical Significance: 5 - Not eligible
 75A Type of Work Proposed:
 75B Work Done by:



Structure Inventory and Appraisal

Bridge ID: STOCKHOLM-130071 FHWA No.: 130071		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 33%;">Official</td> <td style="width: 33%;">SR:</td> <td style="width: 33%;">SD/FO:</td> </tr> <tr> <td>Unofficial</td> <td>SR: 92.8</td> <td>SD/FO: Not Deficient or Obsolete</td> </tr> </table>		Official	SR:	SD/FO:	Unofficial	SR: 92.8	SD/FO: Not Deficient or Obsolete
Official	SR:	SD/FO:							
Unofficial	SR: 92.8	SD/FO: Not Deficient or Obsolete							
IDENTIFICATION 7 Facility Carried: 290TH ST 5B Rte. Signing Prefix: 4 5C Level of Service: 1 - MAINLINE 5D Inventory Route: 0000 City: RURAL 3 County: 024 - Crawford 9 Location: .50 Mi S NW Cor 5-85-38 5E Directional Suffix: 0 - NOT APPLICABLE 6 Feature Intersected: NORSKY CREEK 2 District: 0 Garage: 000 98 Border Bridge Code: % Responsibility: 99 Border Bridge No.:		INSPECTION 80 Inspection Date: 11/09/2015 Next Routine Insp Date: 11/09/2017 Inspection Agency: 2 - County 93A FC Inspection Date: 92A FC Frequency: 93B UW Inspection Date: 92B UW Frequency: 93C SI Date: 92C SI Frequency: Other Non-NBI Date: Other Non-NBI Freq.:							
STRUCTURE TYPE AND MATERIALS 43A Main Span 3 - Steel 43B Main Span Design: 02 - Stringer/Multi-beam or Girder 45 No. Spans Main Unit: 001 44A Appr. Span 000 - NA 44B Appr. Span Design: 000 - NA 46 No. of Appr. Spans: Near 0000 Far 0000 107 Deck Type: 8 - Wood or Timber 108A Wearing Surface: 7 - Wood or Timber 108B Membrane: 0 - None 108C Deck Protection: 0 - None		CONDITION 58 Deck: 9 - Excellent Condition 59 Super: 8 - Very Good Condition (no problems noted) 60 Sub: 9 - Excellent Condition 61 Channel/Channel Prot.: 9 - No noticeable deficiencies 62 Culvert: N - Not Applicable							
GEOMETRIC DATA 48 Length Max Span: 51.5 ft. 49 Structure Length: 52.5 ft. 34 Skew: 0° Deck Area: 1275.75 sq. ft. 50B Curb/Sdwt Width R: ft. 50A Curb/Sdwt Width L: ft. 51 Width Curb to Curb: 24.3 ft. 52 Width Out to Out: 24.3 ft. 32 Appr. Roadway width: 26.0 ft. (w/ Shoulders) 33 Median: 0 - No median 35 Structure Flared: 00 - No flare 10 Vertical Clearance: 99'99" 47 Horiz. Clearance: 24'03" 53 Min. Vert. Clearance Over: 99'99" 54B Min. Vert. Underclearance: 00'00" 55 Min. Lat. Underclearance R: 00'00" 56 Min. Lat. Underclearance L: 00'00"		APPRAISAL 67 Str. Evaluation: 6 - Equal to present minimum criteria 68 Deck Geometry: 6 - Equal to present minimum criteria 69 Underclear Vert & Horiz: N - Not applicable 71 Waterway Adequacy: 8 - Bridge Above Approaches 72 Approach Alignment: 8 - Equal to present desirable criteria 36A Bridge Rail: 0 - DOES NOT MEET CURRENT SAFETY STANDARDS, OR IS NOT THERE AND IS NEEDED. 36B Transition: N - FEATURE NOT REQUIRED 36C Approach Rail: N - FEATURE NOT REQUIRED 36D Approach Rail Ends: N - FEATURE NOT REQUIRED 113 Scour Critical: 8 - Stable - Excellent Condition							
NAVIGATION DATA 38 Navigation Control: 0 - No navigation control on waterway (bridge permit not required) 111 Pier Protection: 2 - In place and functioning 39 Vertical Clearance: " 40 Horiz. Clearance: "		LOAD RATING AND POSTING 31 Design Load: 0 - Unknown 63 Rating Method: 2 - Allowable Stress (AS) reported in english tons using HS-20 loading. 64 Operating Rating: 32.5 Tons 65 Rating Method: 2 - Allowable Stress (AS) reported in english tons using HS-20 loading. 66 Inventory Rating: 27.0 Tons 70 Posting: 5 - Equal to or above legal loads 41 Posting Status: A - Open							
16 Latitude: 42.2035223 17 Longitude: -95.30396239		AGE AND SERVICE 27 Year Built: 2015 Design No.: 0 106 Year Reconstructed: 42A Type of Service on: 1 - Highway 42B Type of Service Under: 5 - Waterway 28A Lanes on: 2 28B Lanes under: 0 29 ADT: 30 30 Year of ADT: 2012 109 Truck ADT: 30 % Speed Limit: 55 19 Detour Length: 4 mi.							
FRA No. (if RR Bridge): Mile Post:		CLASSIFICATION 112 NBIS Length: Y 26 Functional Class: 09 - Rural - Local 100 STRAHNET: 0 - Not a defense highway 101 Parallel Structure: N - No parallel structure 102 Direction of Traffic: 2 - 2-way traffic 22 Owner: 02 - County Highway Agency 21 Custodian: 02 - County Highway Agency 37 Historical Significance: 5 - Not eligible 75A Type of Work Proposed: 75B Work Done by:							