ASS(5) FOLION UP & 7 SCAMNED

Crawford County Recorder Denise Meeves Fee Book 2013-0798

04/05/2013 @10:54AM PLC PLAT CORNER CER Book: Page: \$7.00

Pages: 1

WILKE LAND SURVEYING INC.

401 1800th Street

Pename, lower 51562 (712)489-2898

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

SECTION 36 TOWNSHIP 82N RANGE 41W COUNTY CRAWFORD


Monument Description and Remarks:

Reason for Certificate: (No record Certificate)


NE CORNER - Found 5/8" dia. by 24" rebar with orange cap PLS #17048, 0.50' deep in the bootom of the East road ditch. Corner is in line with fence to the East.

NE CORNER NW1/4 NW1/4 - Set 5/8" dia. by 24" rebor with orange cap PLS \$17048, 0.30' deep in line with fences North, East, & West. Corner is 0.60' Southwest of "X" noils in Southwest face of carner post with fences running North, West, and Forth and East.


NW CORNER - Dug with bockhoe and found broken concrete monument laying sideways from previous dirt work. Set 5/8" dia. by 24" rebor with arange cap PLS #17048 0.70' deep. Corner is an line with the West line of the SW1/4 NW1/4 projected North, and in line with fence to the West. Fits good with WPA chaining distance (15.8') to corner post West.




NW CORNER
SEC. 36, TB2N, R41W
(Set 5/8" dia. by 24" reber
w/orange cap PLS \$17048, 0.7" deep)



NE CORNER NE CORNER
SEC. 38, 182N, R41W
(Find. 5/8" die. by 24" reber
w/orange cap PLS \$17048, 0.5'
deep in bottom of road ditch)



NE CORNER NET /4 NW1/4 SEC. 36, T62N, R41W (Set 5/8" dla. by 24" rebor w/orange cap PLS #17048, 0.3" deep)





List Comer	Corners to be Section		Range
NE CORNER	36	82N	41W
NE CORNER NW1/4 NW1/4	36	82N	41W
NW CORNER	36	82N	41W

nber 17048

My license renewal date is December 31, 2013

Pages or sheets covered by this seal: <u>This rage anti</u>