## UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF

LAND SURVEY MONUMENT SITUATED IN SI		
THE 5TH P.M., <u>CRAWFORD</u> PREVIOUSLY RECORDED IN BOOK,	COUNTY, IOW , PAGE,	OTHER INST. #90-2107
MONUMENT DESCRIPTION AND REMARKS SW COR. NE1/4 SW1/4 - FOUND PK NAIL		
THE MEST CHOWING BELATIVE LOCATION	OF MONIMENT	AND REFERENCE POINTS
PLAN VIEW SHOWING RELATIVE LOCATION	OF MONUMENT	AND REFERENCE POINTS.
'X' NAILS IN PWR POLE	50.00'	<i>y</i>
TRUCK REPAIR BLDG  'X' NAILS IN PWR POLE	5/8" 1.P. SLOPE CHAINED	
SW CORNER NE1/4 SW		15-83-39 RECORDING OFFICER
HEREBY CERTIFY THAT THE SURVEY WORK WAS THIS LAND SURVEYING DOCUMENT WAS PREPARED MY DIRECT PERSONAL SUPERVISION AND THAT I A REGISTERED LAND SURVEYOR UNDER THE LAWS O OWA.  TERENCE E. CRAWFORD	BY ME OR UNDER	FILED DENISON, IOWA CRAWFORD COUNTY  96 JUN - 5 AM 9: 02  MIST. NO. 96 - 1620  DENISE MEEVES. RECORDER  DENISE MEEVES. RECORDER  DENISE MEEVES.
DATE MAY 1 0 19:  IA REG. NO. 8893  EXP. DATE DECEMBER 3	3	FOLLOW UP THE PROOFED