
UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

LAND SURVEY MONUMENT SITUATED IN SECTION 16, T 83 N, R 39 W OF CRAWFORD COUNTY, IOWA. THE 5TH P.M., ____ PREVIOUSLY RECORDED IN BOOK _____, PAGE ____, OTHER MONUMENT DESCRIPTION AND REMARKS W1/4 CORNER - FOUND BROKEN CM 3" DEEP

PLAN VIEW SHOWING RELATIVE LOCATION OF MONUMENT AND REFERENCE POINTS.



W1/4 CORNER SECTION 16-83-39

| I HEREBY CERTIFY THAT THE SURVEY WORK WAS COMPLETED AND THIS LAND SURVEYING DOCUMENT WAS PREPARED BY ME OR UNDER |
|--|
| THIS EARLY SOUTHERN STORMS |
| MY DIRECT PERSONAL SUPERVISION AND THAT I AM A DULY |
| REGISTERED LAND SURVEYOR UNDER THE LAWS OF THE STATE OF |
| |
| IOWA. |
| 70 17 11 |
| |

TERENCE E. CRAWFORD

SEP 3 0 1996

DATE

IA REG. NO. 8893 EXP. DATE DECEMBER 31, 1997

SE PROJECT NO. 0686

SUNDQUIST ENGINEERING, P.C. 120 SOUTH MAIN, P.O. BOX 220 DENISON, IOWA 51442 PH. (712)263-8118

RECORDING OFFICER

FILED DENISON, IOWA CRAWFURD COUNTY

96 OCT 30 PH 3: 16

INST. NO. 96-2978
DEUISE MEEVES. RECORDER Denise Mewer

INDEXED FOLLOW UP PROOFED _