

INDEXED DM
FOLLOW UP BSM
PROOFED DM
SCANNED eg


PREPARED BY - TERENCE E. CRAWFORD - SUNQUIST ENGINEERING - 120 S. MAIN, DENISON, IOWA 51442 - PHONE (712) 263-8118

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF


LAND SURVEY MONUMENT SITUATED IN SECTION 9, T 83 N, R 39 W OF
THE 5TH P.M., CRAWFORD COUNTY, IOWA.
PREVIOUSLY RECORDED IN BOOK _____, PAGE _____, OTHER _____

MONUMENT DESCRIPTION AND REMARKS

N1/4 CORNER - FOUND BROKEN CM WITH 1/4" IRON PIN IN MIDDLE
1.5' DEEP, SET 5/8" DIA. IRON PIN ALONG SOUTH
SIDW OF CM, SET 5/8" DIA. X 6" IRON PIN
W/YELLOW CAP #8893 0.7' DEEP.



PLAN VIEW SHOWING RELATIVE LOCATION OF MONUMENT AND REFERENCE POINTS.



DISTANCES PLUMB CHAINED

N1/4 CORNER SECTION 9-83-39


I HEREBY CERTIFY THAT THIS LAND SURVEYING DOCUMENT WAS PREPARED
AND THE RELATED SURVEY WORK WAS PERFORMED BY ME OR UNDER MY
DIRECT PERSONAL SUPERVISION AND THAT I AM A DULY LICENSED LAND
SURVEYOR UNDER THE LAWS OF THE STATE OF IOWA.

Terence E. Crawford

DEC 11 2009

TERENCE E. CRAWFORD
IA LICENSE NO. 8893

DATE
EXP. DATE DECEMBER 31, 2009



SE PROJECT NO. 23709
DRAWN BY: LLL