

PREPARED BY - TERENCE E. CRAWFORD - SUNDQUIST ENGINEERING - 120 S. MAIN, DENISON, IOWA 51442 - PHONE (712)263-8118

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF

LAND SURVEY MONUMENT SITUATED IN SECTION	
MONUMENT DESCRIPTION AND REMARKS NW CORNER - FOUND 5/8" DIA. REBAR 4" DEEP.	
N1/4 CORNER - FOUND BROKEN CM 1.30' DEEP, RAISED WITH 5/8" DIA. X 8" IRON PIN W/YELLOW CAP #8893 4" DEEP.	
PLAN VIEW SHOWING RELATIVE LOCATION OF MONUMENT AND REFERENCE POINTS.	
"X" NAILS COR. POST "X" NAILS COR. POST "X" NAILS BRACE POST "X" NAILS COR. POST "X" NAILS COR. POST "X" NAILS END POST "X" NAILS END POST "X" NAILS END POST "X" NAILS END POST	
DISTANCES SLOPE CHAINED	DISTANCES PLUMB CHAINED
NW CODNED SECTION 17 97 79	N1 /4 CODNED SECTION 13-83-38

I HEREBY CERTIFY THAT THIS LAND SURVEYING DOCUMENT WAS PREPARED AND THE RELATED SURVEY WORK WAS PERFORMED BY ME OR UNDER MY PIRECT SUPERVISION AND THAT I AM A DULY LICENSED LAND SU DR UNDER THE LAWS OF THE STATE OF IOWA.

Terence E. CRAWFORD

JUL 2 4 2001

TERENCE E. CRAWFORD 1A LICENSE NO. 8893 DATE

EXP. DATE DECEMBER 31, 2001

TERENCE E. CRAWFORD 8893

SE PROJECT NO. 23901
DRAWN BY: LLL