

Crawford County Recorder Denise Meeves Fee Book 2008-3090

11/12/2008 @08:49AM PLC PLAT CORNER CER Book: Page: Total Fees: \$7.00

Pages: 1

PREPARED BY & RETURN TO MIKE SCHULTE, SNYDER & ASSOCIATES, INC. 2727 SW SNYDER ROAD, ANKENY, 10MA 50023 (888) 964-2020


UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF Land Survey Monuments situated in Section 14 Township 37 W , of the Fifth Principal Meridian, CRAWFORD Previously recorded in SEE BELOW) in County Re Previously recorded in (Stt Dolow, Bage, document number, ect.) (Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.) Monument Description and Remarks: SOUTHWEST CORNER NW1/4 SE1/4 NO RECORD OF TIES FOUND SET 1/2" REBAR WITH YELLOW CAP #17979 0.2' ABOVE SURFACE, 3' +/- EAST OF NORTH-SOUTH FENCE LINE AND 0.5' +/- NORTH OF EAST WEST FENCE LINE, BY SINGLE PROPORTIONATE METHOD. NORTHWEST CORNER SW1/4 NE1/4 NO RECORD OF TIES FOUND SET 1/2" REBAR WITH YELLOW CAP #17979 0.2' ABOVE SURFACE, 1.5' +/- WEST OF NORTH-SOUTH FENCE LINE AND 2' +/- SOUTHWEST OF CORNER POST, BY SINGLE PROPORTIONATE METHOD. Plan-View (Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)

NAD83 (1996) Lat: 41°59'52.84925"N Lang: 95°07'15.87129"\


NAD83 (1996) Lat: 42°00'18.82708"N Long: 95°07'15.60747"W



SOUTHWEST CORNER NW1/4 SE1/4 SET 1/2" REBAR 0.2' ABOVE GROUND



NORTHWEST CORNER SW1/4 NE1/4 SET 1/2" REBAR 0.2' ABOVE GROUND



NOTE: ALL DISTANCES MEASURED HORIZONTAL



to site My License Renewal Date 1s Dec

es or sheeks opvered by this seci-SHEET 10F 1

List Corners to be Indexed

		Corners		Section	Twp	Range
	S₩	COR NW1/4	SE1/4	14	83	37
-	NW	COR SWI/4	NE1/4	14	83	37

TECH: MLS/SLG DATE: 10/28/08 PN: 83-37-14-SW COR NW SE & NW COR SW NE 108.0781