

PREPARED BY: MICKAEL BERNDT CRAWFORD COUNTY ENGINEERS OFFICE - COURTHOUSE - DENISON, IA. - 712-263-2449

## UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF

LAND SURVEY MONUMENT SITUATED BETWEEN SECTIONS 9 & 10, T 85 N, R 40 W THE 5TH P.M. CRAWFORD COUNTY, IOWA.


PREVIOUSLY RECORDED IN BOOK N/A , PAGE , OTHER


## MONUMENT DESCRIPTION AND REMARKS

WEST1\4 CORNER SEC.10-85-40

This comer was not set by the government surveyors during the original survey of Morgan Township. The comer was established by the split of the NW Cor. Sec.10-85-40 and the SW Cor. Sec.10-85-40 and the split of the fences compared to the split of the road. The original road #119 was established in 1874. Crawford County was constructing a weir and needed the corner for easement purposes.


WEST 1\4 CORNER SEC. 10-85-40 SET 5\8" X 18" REBAR **RED CAP #11982** 6" DEEP





CORNER: W1\4 SECTION: 10

TOWNSHIP: 85N RANGE: 40W



I HEREBY CERTIFY THAT THIS LAND SURVEYING DOCUMENT WAS PREPARED AND THE RELATED SURVEY WORK WAS PERFORMED BY ME OR UNDER MY DIRECT PERSONAL SUPERVISION AND THAT I AM A DULY LICENSED LAND SURVEYOR UNDER THE LAWS OF THE STATE OF IOWA.

". J. ÁSSMAN

IA. LICENSE NO. 11982

EXP. DATE 12-31-02

