## SECTION CORNER CERTIFICATE

LAND SURVEY MONUMENT SITUATED IN SECTION ZO, T82 N, R38 W OF THE 5TH P.M., CRANFORD COUNTY, IOWA.  PREVIOUSLY RECORDED IN BOOK, PAGE, OTHER	
DESCRIPTION OF EVIDENCE FOUND  N W COR FOUND LEAD PLUC 1	N PAVEMENT I
NW COR FOUND ICON PIN	
WKy COR FOUND BROKEN C.M.	
SET 5/8" IRON PIN	) 4" DEEP \ _ ' _ \ _ ' _ \
SKETCH SHOWING RELATIVE LOCATION OF MONUM MONUMENT AND/OR ACCESSORIES ESTABLISHED.	ENT AND REFERENCE POINTS. DESCRIPTION OF
5 68 CM CM 141	'X' NAILS IN WOOD POSTS SLOPE CHAINED ZND
N /4 COR. SECTION 20-82-38	POST 31.80 38.00 POST
CM CM CM	FG POST POST POST
26 12 14 CM CM CM	
NW COR. SECTION 20-82-38	WK4 COR. SECTION 20-82-38
I HEREBY CERTIFY THAT THE SURVEY WORK WAS CENTRED AND SURVEYING DOCUMENT WAS PREPARED MY DIRECT PERSONAL SUPERVISION AND THAT I AN REGISTERED LAND SURVEYOR UNDER THE LAWS OF IOWA.	BY ME OR UNDER
Terence Strawford	
Terence E. Crawford	
date 7-3/-95	
la reg. no. 98°	<u>'&gt;                                    </u>