INDEXED LO FOLLOW UP __ PROOFED ___ SCANICED ___

Instrument #: 2015-0696 04/08/2015 11:08:01 AM Total Pages: 1 PLC PLAT CORNER CER Recording Fee: \$7.00 Transfer Tax: \$0 Denise Meeves, Recorder, Crawford County Ioua

PREPARED BY J. SCOTT SHEVEL PLS, I&S GROUP, P.O. BOX 458 1725 N. LAKE AVE. STORM LAKE, IOWA 50588 TELEPHONE (712)732-6292	
UNITED STATES PUBLIC LAND SURVEY CORNER CER	TIFICATE (2.) 3.)
LAND SURVEY MONUMENTS SITUATED IN SECTION 6	
TOWNSHIP 85 NORTH, RANGE 38	_west
OF THE 5TH P.M., CRAWFORD COUNTY, IOWA.	R-38-W
▲ = SECTION CORNER FOUND	
SURVEY MARKER - 1-1/2" YELLOW/ORANGE PLASTIC TO SURVEY MARKER - 1-1/2" YELLOW/ORANGE PLASTIC DISK AS SHOWN	C (SOME PLANE) REFERENCE BAR SET - 1/2" REBAR W/BLUE PLASTIC CAP AS SHOWN
1.) W 1/4 CORNER 6-85-38: FOUND 5/8" REBAR APPROX. 17" WEST OF © IA. HWY. 39 set 1/2" reber wisedion corner ref. cap 5 side PP ref. cap 5 side PP conc. MONUMENT WISENT REBAR AT SURFACE OF GRAVEL ROAD. 1.) W 1/4 CORNER 6-85-38: FOUND 5/8" REBAR APPROX. 17" WEST OF © IA. HWY. 39 RAW rail 106.73" 106.73" RAW rail 106.73" Conc. monument wireber 108.73" Conc. monument wireber 108.73" Conc. monument wireber	
3.) N1/4 CORNER 6-85-38: FOUND SHAFT OF PK NAIL APPROX. 4' SOUTH OF CENTERLINE IA. HWY. 39 UNDER ASPHALT. REMOVED AND REPLACED WITH SHORT PIECE OF 1/2" REBAR WITH 1-1/2" ALUM. CAP.	
fd. rebar by fd. RAVW crange post	
THIS CERTIFICATE WAS PREPARED BECAUSE NO CERTIFICATE FOR THE CORNER(S) REFERENCED HEREON IS OF RECORD IN THE OFFICE OF THE CRAWFORD COUNTY RECORDER	
I hereby certify that this land surveying document was	List Corners to be Indexed
prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly	Corners Section Twp. Rng.
licensed Land Surveyor under the laws of the State of lowa.	1.) W 1/4 6 85 38
SHEVEL OF () () XX /Y X Y/3/14	2.) NW 6 85 38
J. Scott Shevel Date:	3.) N 1/4 6 85 38
License Number 11810 My license renewal date is December 31, 2015 Pages covered by this seal 1	PN: 15-17661 DRAWN: JSS