WILKE LAND SURVEYING INC.

401 1800th Street

Panama, lowa 51562

(712)489-2898


UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

SECTION 20 TOWNSHIP 85N RANGE 39W COUNTY CRAWFORD

Reason for Certificate: (No record Certificate)

Monument Description and Remarks:

CENTER — No record for this corner was found at the County Engineer's Office. No evidence of ties or a monument was found on site. Calc'd an intersection point of lines connecting opposite 1/4 Corners to compare to the fence intersection point, with fences North, East, & West. Set 5/8" dia. by 24" rebar with orange cap PLS #17048 (0.4' deep) at the projected intersection of fences as the best evidence of the Center of the Section.





"X" nails Southeast face corner post leaning Northwest.

"X" nails top of fence post.

9.96'

"X" nails South face fence post.

*(All distances are plumb)

SET 5/8" DIA. REBAR W/ORANGE CAP PLS #17048 (0.4' DEEP).

DEAN A STATE OF THE PROPERTY O

i hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that i am a duly licensed Land Surveyor under the larm of the State of loan.

Danie Oli

License number 17048

My Roense renswal date is December 31, 2011

Pages or sheets covered by this seal: This page only

	List C	orners	to	be	Index	ed
Corner		Section		Tw	p.	Range
CENTER		20		85	SN .	39W