UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF
LAND SURVEY MONUMENT SITUATED IN SECTION <u>25</u> , T <u>85</u> N, R <u>39</u> W OF THE 5TH P.M., <u>CRAWFORD</u> COUNTY, IOWA. PREVIOUSLY RECORDED IN BOOK, PAGE, OTHER <u>92-0636</u>
MONUMENT DESCRIPTION AND REMARKS
N1/4 CORNER - FOUND 1/2" REBAR 4" DEEP
NE CORNER - SET IRON PIN W/CAP #8893 6" DEEP FROM TIES & PREVIOUS SURVEY INFORMATION
PLAN VIEW SHOWING RELATIVE LOCATION OF MONUMENT AND REFERENCE POINTS.
'X' NAILS FE. POST TOP CTR. TEL. PED. 'X' NAILS COR. POST SLOPE CHAINED
45.50' 'X' NAILS 'X' NAILS 'X' NAILS BRACE POST BRACE POST WI MAILS WI MAILS WI MAILS WI MAILS WI MAILS WI MAILS

I HEREBY CERTIFY THAT THE SURVEY WORK WAS COMPLETED AND THIS LAND SURVEYING DOCUMENT WAS PREPARED BY ME OR UNDER MY DIRECT PERSONAL SUPERVISION AND THAT I AM A DULY REGISTERED LAND SURVEYOR UNDER THE LAWS OF THE STATE OF IOWA.

'X' NAILS BRACE POST

N1/4 CORNER SECTION 25-85-39

urences

COR. POST

'X' NAILS

PWR. POST

JUL 0 5 1996

DATE

TERENCE E. CRAWFORD

E.CRAH

IA REG. NO. 8893 EXP. DATE DECEMBER 31, 1997

SE PROJECT NO. 2346

SUNDQUIST ENGINEERING, P.C. 120 SOUTH MAIN, P.O. BOX 220 DENISON, IOWA 51442 PH. (712)263-8118

RECORDING OFFICER
FILED DENISON, IOWA
ORAGIEORD COUNTY

NE CORNER SECTION 25-85-39

'X' NAILS

PWR. POST

96 AUG -2 PM 12: 55 INIST. NO. 96-2220

INDEXED FOLLOW UP PROOFED _