
## UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF

LAND SURVEY MONUMENT SITUATED IN SECTION5, T85N, R39W OF THE 5TH P.M.,CRAWFORDCOUNTY, IOWA.  PREVIOUSLY RECORDED IN BOOK, PAGE, OTHER	
MONUMENT DESCRIPTION AND REMARKS  NW CORNER - SET 5/8" IRON PIN W/CAP #8893 0.3' DEEP, SET FROM LOCAL EVIDENCE	
SW CORNER – FOUND 5/8" IRON PIN 3" DEEP OVER 1" PIN 20" DE	EP

PLAN VIEW SHOWING RELATIVE LOCATION OF MONUMENT AND REFERENCE POINTS.



NW CORNER SECTION 5-85-39

'X' NAILS IN BRACE POST X' NAILS IN COR. POST 'X' NAILS IN 'X' NAILS IN PWR. POLE 'X' NAILS IN TOP CTR. TELE. PED. SLOPE CHAINED DISTANCES

SW CORNER SECTION 5-85-39

I HEREBY CERTIFY THAT THE SURVEY WORK WAS COMPLETED AND THIS LAND SURVEYING DOCUMENT WAS PREPARED BY ME OR UNDER MY DIRECT PERSONAL SUPERVISION AND THAT I AM A DULY LICENSED LAND SURVEYOR UNDER THE LAWS OF THE STATE OF IOWA.

prence c

NOV 2 2 1996

DATE

TERENCE E. CRAWFORD &

IA LICENSE NO. 8893 EXP. DATE DECEMBER 31, 1997

SE PROJECT NO. 2526

& LAND

SUNDQUIST ENGINEERING, P.C. 120 SOUTH MAIN, P.O. BOX 220 DENISON, IOWA 51442 PH. (712)263-8118

RECORDING OFFICER

FILED DEHISON, IOWA CRAWFORD COUNTY

96 NOV 26 AN 10: 07 MST.4096-3236 DENISE MEEVES. RECORDER Denie Meevee 6.00

INDEXED FOLLOW UP PROOFED.