
06/09/2008 @02:33PM PLC PLAT CORNER CER Book: Total Fees: Page: \$7.00



WILKE LAND SURVEYING INC. 401 1800th Street

Panama, Iowa 51562

(712)489-2898


UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

SECTION 20 TOWNSHIP 83N RANGE 40W COUNTY CRAWFORD


Certificate Prepared For: Survey of Lot 1 of the W1/2 SW1/4 (No record corner certificate for these corners)

Monument Description and Remarks:

- 1)- Farmer has put down some old slated concrete hog shed floor w/rebar in them, starting in the road and extending into the farm field driveway to the Southeast. No record of a WPA concrete monument, just a nail for this corner. Set a ½" dia. by 24" rebar w/orange cap PLS #17048 (0.3' deep) by local evidence being the fence lines South & East.
- (2) Found concrete monument w/brass disc (flush) 1' from the top edge of a deep creek to the North. Set a rebar along the South edge for detection purposes. The monument will eventually fall into the creek with erosion.








I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Land Surveyor under the laws of the State of lowa.


Dean A. Wilke

License number 17048

My license renewal date is December 31, 2009

Pages or sheets covered by this seal: This page only





List Corners to be Indexed				_
<u>Corner</u>	Section	Twp.	Range	-
SW CORNER	20	83N	40W	
S1/4 Corner	20	83N	40W	