

INDEXED DD CP
 RECORDED _____
 FILED _____
 SEARCHED _____

Prepared by: Nathan H. Carlson Address: 3701 12th Street N, Suite 206, St. Cloud, MN 56303 Phone: 320-253-9495

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE FOR

Land survey monuments situated in Section 14, Township 85N
 Range 41W, of the Fifth Principal Meridian, Crawford County, Iowa.

Previously recorded in _____ in County Recorder's Office.



(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions & monumentation found or placed.)

MONUMENT DESCRIPTION AND REMARKS: 1939 notes from the Highway Department indicate a concrete monument was placed at the corner position and reference ties were established. The notes also indicate that in 1989, the remains of the concrete monument were replaced with a 3/4" capped pipe. A search of the area was made and no monuments were found at the corner location, however 5 of the 6 1939 reference ties were in place. Using the reference ties, a 1/2" rebar with LS cap 19314 was placed at the corner location and all ties were updated as noted below.

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)

* ALL TIES ARE "X" NAILS IN WOOD FENCE POSTS.



SLST-3/98

I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Land Surveyor under the laws of the State of Iowa.

Nathan H. Carlson 1/4/2012
 Signature Date

Typed/Printed Name: Nathan H. Carlson
 License Number: 19314
 My license renewal date is December 31, 2012
 Pages or sheets covered by this seal: This sheet

Corners to be Indexed

Corners	Section	Twp.	Range
N1/4	14	85N	41W