Prepared by: __Nathan H. Carlson__ Address: ___3701 12th Street N, Suite 206,___ Phone: __320-253-9495__
St. Cloud, MN 56303

## UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE FOR

Land survey monuments situated in Section _____27_____, Township ____·85N____

_____ Range ____41W____, of the Fifth Principal Meridian, ___Crawford___ County, Iowa.

Previously recorded in _____ in County Recorder's Office.

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions & monumentation found or placed.)

MONUMENT DESCRIPTION AND REMARKS: _Searched the area and found a bent nail_
at the intersection of the road centerlines. Measured 2637.49 feet to the E1/4 corner of Sec. 27.
Accepted the nail as marking the position of the corner and replaced it with a 1/2" rebar with LS cap
19314. Established reference ties as noted below.

PLAN -- VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)

I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Land Surveyor under the laws of the State of Iowa.

Signature _____ Date __1/4/2012__

Typed/Printed Name: __Nathan H. Carlson__

License Number: __19314__

My license renewal date is December 31, __2012__.

Pages or sheets covered by this seal: __This sheet__

SEAL — NATHAN CARLSON 19314 IOWA — LICENSED LAND SURVEYOR

Corners to be Indexed			
Corners	Section	Twp.	Range
NE	27	85N	41W

SLS1-3/98