

Crawford County Recorder Denise Fee Book 2007-0948 REC014092 04/11/2007 #1130AM # Pages 1 PLC PLAT CORNER CER Total Fees: \$7.00

WILKE LAND SURVEYING INC.

401 1800th Street

Panama, Iowa 51562

(712)489 - 2898

## UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

SECTION 1 TOWNSHIP 85N RANGE 38W COUNTY CRAWFORD

Certificate Prepared For: Survey of Lot 2 of the SE1/4 SE1/4

Monument Description and Remarks:


On previous survey dug with backhoe in line with fence North perpendilar to road. Nothing was found, set %" dia. x 24" rebar w/orange PLS #17048 (0.4' deep) on line between SW Corner & SE Corner of Section and in line with fence

North. Hit centerline of road close.


2 - Found conc. mon. w/bross disc (0.7' deep).
Set rebar along side for detection purposes.
3 - After checking how the intersection point of lines from opposite 1/4 Corners compared to the existing fence corner post at the center of Section, set a ½" by 24" rebar w/orange cap PLS #17048 (flush) on the South side of

the corner post and used that point as the center of Section.


(4) - Set %" by 24" rebar w/orange cap PLS #17048 (1.0' deep) at the intersection point of lines from the midpoints of opposite sides of the










List <u>Corner</u>	Corners Section	to be Index Twp.	xed Range
S1/4 CORNER	1	85N	38W
N1/4 CORNER	1	85N	38W
CENTER	1	85N	38W
NW CORNER SE1/4 SE1/4	1	85N	38W









I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Land Surveyor under the laws of the State of lowa.

License number 17048

My license renewal date is December 31, 2007

Pages or sheets covered by this seal: This page only