

PREPARED BY - PAUL J. ASSMAN - LICENSED LAND SURVEYOR - DENISON, IOWA 51442 - PHONE (712)263-8747

## UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE


OF

LAND SURVEY MONUMENT SITUATED IN SECTION 18 , T 82 N, R 38 W OF CRAWFORD \_\_\_\_COUNTY, IOWA. THE 5TH P.M.,\_ \_\_\_\_, OTHER PREVIOUSLY RECORDED IN BOOK \_\_ \_, PAGE \_\_


MONUMENT DESCRIPTION AND REMARKS

NW CORNER - FOUND BRASS CAP IN MONUMENT 20" DEEP

W 1/4 CORNER - FOUND 5/8" REBAR 6" DEEP



PLAN VIEW SHOWING RELATIVE LOCATION OF MONUMENT AND REFERENCE POINTS 35' 33'



"X" NAILS COR. POST CORNER IS 1.5' NORTH OF FENCE TO THE WEST

"X" NAILS "X" NAILS TOP FENCE POST BRACE POST 34.35 **3**7.10' 32.68 "X" NAILS TOP GATE POST 38.10 42.28 "X" NAILS TOP "X" NAILS POWER POLE BRACE POST

DISTANCES SLOPED CHAINED W 1/4 CORNER SECTION 18-82-38

DISTANCES SLOPED CHAINED NW CORNER SECTION 18-82-38

I HEREBY CERTIFY THIS LAND SURVEYING DOCUMENT WAS PREPARED AND THE RELATED SURVEY WORK WAS PERFORMED BY ME OR UNDER MY DIRECT SUPERVISION AND THAT I AM A DULY LICENSED LAND SURVEYOR UNDER THE LAWS OF THE STATE OF IOWA.

PAUL J. ASSMAN

IA LICENSE NO. 11982

DATE EXP. DATE DECEMBER 31, 2002

ASSMAN 11982

DRAWN BY SJW