
UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

LAND SURVEY MONUMENT SITUATED IN SECTION 18, T 82 N, R 39 W OF THE 5TH P.M., __ CRAWFORD COUNTY, IOWA. PREVIOUSLY RECORDED IN BOOK _____, PAGE _____, OTHER_


MONUMENT DESCRIPTION AND REMARKS

NE CORNER - FOUND LEAD PLUG IN PAVEMENT SET PK NAIL IN LEAD PLUG

E1/4 CORNER - SET 5/8" IRON PIN W/CAP #8893 9" DEEP, SET ON LINE BETWEEN NE COR. & SE COR. OF SECTION 18 AND ON LINE WITH FENCE LINE EAST & WEST



PLAN VIEW SHOWING RELATIVE LOCATION OF MONUMENT AND REFERENCE POINTS.



I HEREBY CERTIFY THAT THIS LAND SURVEYING DOCUMENT WAS PREPARED AND THE RELATED SURVEY WORK WAS PERFORMED BY ME OR UNDER MY DIRECT SUPERVISION AND THAT I AM A DULY LICENSED LAND SURVEYOR UNDER THE LAWS OF THE STATE OF IOWA.

TERENCE E. CRAWFORD

MAR 08 2000

IA LICENSE NO. 8893

NE CORNER SECTION 18-82-39

DATE

EXP. DATE DECEMBER 31, 2001

ENGR. & TERENCE E. CRAWFORD 8893

E1/4 CORNER SECTION 18-82-39

SE PROJECT NO. 21800