


16

Dug hole 20x4x2' para 101 to row

of cottonwoods. Found granite rock 11-9-4.
at 2' with 1/2 x 2 x 2 stake badly rotted 1' W



5-10-73 (Eve)
6-10-71 Instr. Ties (Krusel)

All distances Plumb Connected

36

Dug hole 2x2' and found rock 1/4 x 1/4 x 1/4
at a depth of 2" below road surface

1 Cedar stake 6" long badly decayed
Lowered and set CM

Ties from X-spts

48.6 SW from Cor Post


30.3 N.W. " " Steel Post

27.6 N " " Cor Post

28.8 S " " Cor Post

7-2-73 Set lead plug Found 7-23-41

17 Payment from Instn 7/2/57 OK
Ties EKLHMAN, FARMER, CASE
FORM



12-7-71 Set 3/4" bolt from
Instn ties 12" deep
Set New X-TIES
Krusel, EKLHMAN, BERRY
10" deep

5-36-F

Found 6-14-39

