

No. 00 of _____
 FOLLOW UP _____
 FLOODED _____
 SURVEIL _____

PREPARED BY & RETURN TO MIKE SCHULTE, SNYDER & ASSOCIATES, INC. 2727 SW SNYDER ROAD, ANKENY, IOWA 50023 (515) 964-2020

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF

Land Survey Monuments situated in Section 07, Township 83 N, Range 41 W, of the Fifth Principal Meridian, CRAWFORD, County, Iowa.
 Previously recorded in N/A In County Recorder's Office.
 (book, page, document number, ect.)

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)

Monument Description and Remarks:

SE CORNER SECTION 7-83-41



NO CORNER CERTIFICATE ON FILE. USED COUNTY ENGINEER'S TIES TO FIND 5/8" REBAR WITH YELLOW PLASTIC CAP #5798 (8" DEEP). CERTIFICATE IS BEING FILED BECAUSE THERE IS NOT ONE ON RECORD.

Plan-View

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)

NAD 83/IA RTN Derived
 Lat: 42°00'30.11131"N
 Long: 95°39'12.22445"W
 Elevation: 1363.85
 CSF: 0.999950349

SE CORNER
 FOUND 5/8" REBAR WITH
 YELLOW PLASTIC CAP #5798
 (8" DEEP)



NOTE: ALL DISTANCES MEASURED HORIZONTAL UNLESS OTHERWISE NOTED. S&A 1

I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Land Surveyor under the laws of the State of Iowa.

Mike Schulte Date: 08/15/11
 Mike Schulte, PLS

License Number: 17979
 My License Renewal Date is December 31, 2011

Pages or sheets covered by this seal:
 SHEET 1 OF 1

List Corners to be Indexed

Corners	Section	Twp	Range
SE	7	83	41
SW	8	83	41
NW	17	83	41
NE	18	83	41

TECH: MLS/JCC PN: 83_41_07_SE 111.0616 DATE: 08/15/11