
PREPARED BY - JOSEPH P. RUESCHENBERG - SUNDQUIST ENGINEERING - 120 S. MAIN, DENISON, IOWA 51442 - PHONE (712) 263-8118


UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

<u>. </u>
LAND SURVEY MONUMENT SITUATED IN SECTION 9, T 83 N, R 41 W OF THE 5TH P.M., CRAWFORD COUNTY, IOWA. PREVIOUSLY RECORDED IN BOOK, PAGE, OTHER
MONUMENT DESCRIPTION AND REMARKS
NW CORNER - FOUND BROKEN CM 2.3' DEEP W/PIECES OF BRICK & 6" X 6" ROCK, RAISED WITH 5/8" DIA. X 18" IRON PIN W/ORANGE CAP #14709 0.8' DEEP.
SW CORNER - SET 5/8" DIA. X 18" IRON PIN W/ORANGE CAP #14709 0.6' DEEP, RESET FROM OLD COUNTY TIES.
PLAN VIEW SHOWING RELATIVE LOCATION OF MONUMENT AND REFERENCE POINTS.



DISTANCES PLUMB CHAINED

NW CORNER SECTION 9-83-41



SW CORNER SECTION 9-83-41

HEREBY CERTIFY THAT THIS LAND SURVEYING DOCUMENT WAS PREPARED AND THE RELATED SURVEY WORK WAS PERFORMED BY ME OR UNDER MY DIRECT PERSONAL SUPERVISION AND THAT I AM A DULY LICENSED LAND SURVEYOR UNDER THE LAWS OF THE STATE OF IOWA.

OCT 2 9 2007 JOSEPH P. RUESCHENBERG DATE

EXP. DATE DECEMBER 31, 2008

ENGR. & LAN JOSEPH P. RUESCHENBERG 14709 AWO\

SE PROJECT NO. 24907 DRAWN BY: ____

IA LICENSE NO. 14709